

*If you are using a printed copy of this procedure, and not the on-screen version, then you **MUST** make sure the dates at the bottom of the printed copy and the on-screen version match. The on-screen version of the Collider-Accelerator Department Procedure is the Official Version. Hard copies of all signed, official, C-A Operating Procedures are available by contacting the ESSHQ Procedures Coordinator, Bldg. 911A*

C-A OPERATIONS PROCEDURES MANUAL

15.3.2.9 Test Procedure for BNL Booster Corrector

(Booster/AGS Ring Power Supply Systems Group Procedure EPS-B-009)

Note: This document was formerly a C-A Group Procedure. The content of the group procedure was reviewed by the Technical Supervisor. All approvals and/or issue dates of the original group procedure are maintained for present use.

Hand Processed Changes

<u>HPC No.</u>	<u>Date</u>	<u>Page Nos.</u>	<u>Initials</u>
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Approved: _____
Signature on File
Collider-Accelerator Department Chairman

Date

M. Bannon

Booster/AGS Ring Power Supply Systems
Group Procedure EPS-B-009
Revision 00

TEST PROCEDURE FOR BNL BOOSTER CORRECTOR POWER SUPPLIES

- 1) Calibrate Power Supply's locally.
- 2) Check remote ----- reference
----- readbacks
- 3) Check "Iout" ----- magnet current
----- external shunt

remote reference-	+10 v	Vref	+Iout (max)
	0 v	Vref	Iout=0amps
	-10 v	Vref	-Iout (max)

BOOSTER CORRECTOR POWER SUPPLY CALIBRATION PROCEDURE

Note:

Use test rack to perform power supply testing and troubleshooting.

Note:

Use proper safety procedures while performing tests

- 1) Disconnect the magnet from power supply output and install shunt (ex.=75amps/100millivolt) in series with load.
- 2) Connect the 9 pin "D" connector into the back of power supply (BNC's on the front of the test rack are ref input and analog out from 9 pin connector.
- 3) Plug in all connectors in the back of power supply to test rack.
- 4) Install water hose connections to the power supply and cool transistor banks inside power supply with external water.

DCCT zero adjustment

- 5) Hook DVM (+) to TP 5 (refer to TP location sheet) and DVM (-) to capacitor C20 (- side). Set DVM to DC millivolt range.
- 6) Set the Local/Remote Switch on the front of the power supply to **local**. Using the controls on the front of the test rack bring the power supply to **standby**. Allow the power supply to warm up for approx. 2 minutes before zeroing the **DCCT**.
- 7) Adjust **R29** pot so that the DVM indicates 0 millivolts.

IDLE current adjustment (You will need 2 DVM's to do this test.)

Note:

This is a critical adjustment to avoid thermal runaway on transistors.

- 8) Set-up DVM #1 to read DC current (10amps max.) Then remove fuse #1 (fuse to + cap bank) and install DVM #1 meter leads in place of fuse.
- 9) Hook DVM#2 to front power supply BNC (Iout) set DVM to DC millivolt range.

Note:

If PCB has never been set-up before turn pots R68 & R84 CCW all the way, then turn each pot CW 12 turns. This will put you in the ball park adjustment before the actual Idle current adjustment is made.

- 10) Bring power supply to **Standby**, then **On**
- 11) Adjust R68 (positive transistor bank) and R84 (negative transistor bank) to obtain .50 amps on DVM#1 and 1-2millivolts on DVM#2.

Note:

Adjust each pot a ¼ turn at a time watching DVM#2 stays within +/- 1.2 millivolts. If reading become to negative adjust pot R68 for more positive current. If readings become more positive adjust pot R84 for more negative current. Increment between the two pots until DVM#1 is .50amps and DVM#2 is 1.2 millivolts.

- 12) After Idle adjustment is made turn power supply Off and reinstall fuse #1.

Caution:

Be careful cap bank buss is not charged.

DCCT calibration (You will need 4 DVM's to do this test.)

- 13) Hook DVM#1 to the shunt output BNC. Set DVM to DC millivolt range.
- 14) Hook DVM#2 to TP 5 and com(C20 [-]). Set DVM to DC volts range.
- 15) Hook DVM#3 with a BNC Tee to Analog Input BNC on front of test rack. Set to dc volt range.
- 16) Hook DVM#4 to Analog output BNC on front of test rack. Set to dc volt range.
- 17) Hook a datel precision voltage source to the Analog input BNC Tee (from step15) (ref needs to swing +/- 10 volts Dc) and set it to zero volts.
- 18) Turn power supply to "Stand-by", then to "On".
- 19) Adjust the +/- 10 volt analog ref so that DCCT reads 5.000v @ TP5. (DVM #2) note: this should be max current output of power supply ex. 5.000vdc on DCCT = _____ millivolt on shunt(.75amps / 1 millivolt)
- 20) Adjust R22 to calibrate Shunt current (DVM#1) to the DCCT current (DVM #2). Check linearity of DCCT to current at 5 steps 0.0v, 1.0 v, 2.0v, 3.0v, 4.0v, 5.0v record current at each DCCT setting.

Calibrate Analog Output to Computer

- 21) DVM # 4 is looking at the analog output BNC. It should read 2x that of DVM # 2. (TP5) if not adjust R11pot until it reads a 2x DVM # 2.

Calibrate Computer Reference (Analog Input)


- 22) Adjust R40 pot so that the voltage read at the junction of R38 and R41 is exactly ½ of what the analog reference is which is presently being sent from the datel. (Step #17)
- 23) Run analog reference as follow: + 10v = max (+) output current
 Zero = zero output current
 -10v = max (-) output current
- 24) Adjust R44 so that the shunt current reads the maximum power supply output current at the +10v ref. If you run out of adjustment on R44 refer to the following note.

Note:

R44 has a 10 millivolt range. If the desired output current could not be reached with the +10 v analog ref, input then set R44 to its mid point and adjust R40 so the desired output current is achieved with +10vdc analog ref input.

- 25) Run the analog ref to zero and the shunt should read zero millivolt.
- 26) Run the analog ref to -10vdc and the shunt should read max negative current
- 27) Run the analog ref back to + 10vdc and recheck the max positive current.
- 28) Now run power supply from + 10vdc to zero then to -10 vdc in 9 steps and record the linearity of the ref. vs current output. (ref @ +10.0v, +7.50v, +5.0v, +2.50v, 0.0v, -2.50v, -5.0v, -7.50v, -10.0v)
- 29) Hook scope up to Analog output BNC and Analog input BNC.
- 30) Hook a function generator up to Analog ref BNC able to swing from +10vdc to -10vdc.
- 31) Make sure power supply tracks reference without any oscillations.
- 32) Check the slew rate board if power supply is equipped and make sure it is set for 0 to +10v in 0 to 10msec. (except for the skew quad it's slew is 0 to +10v in 0 to 20msec.)
- 33) Adjust the DC over current by running power supply approx 1 to 2 amps over its rated output and adjust R105 until power supply trips off on DC over current.

Test Points and Pots Locations in Orbit PCBoard



Test Points	
Tp1	-Thermistor Bank #1
Tp2	-Thermistor Bank #2
Tp3	-Temperature Limit Setup
Tp4	-U7 Out (Analog In/2)
Tp5	-Over Current (U5 after Gain & Balance)
Tp6	-Transistor Over-Temperature
Tp7	-Error Out
Tp8	-Regulator Error
Tp9	-DC Over-Current
Tp10	-Driver 1
Tp11	-Commun
Tp12	-Driver 2
	R11 -Calibration Analog Out
	R12 -Gain Cal Out
	R15 -Offset Pot Out
	R22 -DCCT Gain
	R29 -DCCT Zero Adjust
	R33 -Offset Pot In
	R40 -Analog In Gain
	R44 -Analog In Balance
	R51 -Analog In Zero Adjust
	R68 -Pos. Idle Current Calibration
	R84 -Negative Idle Current Cal.
	R105 -Over Current Limit
	R118 -Regulator Error
	R133 -Temperature Limit Cal.

Page 1 of 1---04/16/03

File://galarraga/C:/Documents and Settings/My documents/galarraga/**BNL Related DOC/OrbitPCB**